



Illinois Department of Transportation

2300 South Dirksen Parkway / Springfield, Illinois / 62764

To: Users of the Highway Standards

Subject: Revision #211

Date: September 25, 2009

Revision #211 of the Highway Standards, effective January 1, 2010, is now available on the Department's website: <http://www.dot.il.gov/desenv/hwystds/HwyStndIndex.html>.

The revisions are as follows:

<u>Removed</u> Standards by Subject/Title January 1, 2009	<u>Inserted</u> Standards by Subject/Title January 1, 2010	<u>Remarks</u> Updated.
Division 200 Index January 1, 2009	Division 200 Index January 1, 2010	Updated.
280001-04	280001-05	Added J-hooks to silt filter fence. Added detail for attachment of two silt filter fences. Modified Aggregate Ditch Check.
Division 300 Index January 1, 2009	Division 300 Index January 1, 2010	Updated.
Division 400 Index January 1, 2009	Division 400 Index January 1, 2010	Updated.
420401-07	420401-08	Added reference to improved subgrade.
Division 500 Index January 1, 2009	Division 500 Index January 1, 2010	Updated.
542536-02	542536-03	Corrected 3'-11" vertical dimension line in Section A-A.
542601-01	542601-02	Corrected inside dimension line for pipe diameter.
Division 600 Index January 1, 2009	Division 600 Index January 1, 2010	Updated.
609001-04	609001-05	Added bolt-down feature to frame and grate. Omitted steel frame.

<u>Removed</u>	<u>Inserted</u>	<u>Remarks</u>
609006-04	609006-05	Added bolt-down feature to frame and grate. Omitted steel frame. Modified Section A-A.
610001-04	610001-05	Added bolt-down feature to frame and grate. Omitted steel frame.
631006-06	631006-07	Increased steel tube length and corrected hole locations in tube.
631011-05	631011-06	Corrected hole locations in steel tube.
631031-07	631031-08	Omitted parapet wood block-out. Reduced curb length to 15'. Added alternate post size.
631032-04	631032-05	Corrected dimension on connection angle with regard to hole spacing. Added alternate post size.
Division 700 Index January 1, 2009	Division 700 Index January 1, 2010	Updated.
701400-03	701400-04	Added note to omit signs mounted in median when median width is less than 10' (3 m).
701411-05	701411-06	Added General Note to allow omission of pavement marking tape for work not exceeding three days.
701451	701451-01	Corrected dimension portion of sign numbers.
704001-05	704001-06	Revised General Notes to refer to Standard 635011 for dimensions of Type C marker.
Division 800 Index January 1, 2009	Division 800 Index January 1, 2010	Updated.
	825001	New standard.
	825006	New standard.

<u>Removed</u>	<u>Inserted</u>	<u>Remarks</u>
	825011	New standard.
	826016	New standard.
	825021	New standard.
	825026	New standard.
	836001	New standard.
	837001	New standard.
878001-07	878001-08	Revised note for foundation depth in table. Revised sizes of rebars.
Division 000 Index January 1, 2009	Division 000 Index January 1, 2010	Updated.
Division BLR Index January 1, 2009	Division BLR Index January 1, 2010	Updated.
BLR-26-1	BLR 26-2	Changed post length from 6'-9" to 6'-0". Modified table on sheet 4.

Questions regarding the Highway Standards should be directed to the Policy and Procedures Section in the Bureau of Design and Environment at 217-524-9311.

Sincerely,



Charles J. Ingersoll
Engineer of Design and Environment